



eDART conx™

Process Control

Software v10 Manual

i **NOTE** eDART® Process Control Software version 10 is compatible ONLY with the following touchscreen:
Model: 1715L, MFG Part #: E603162, CDW Part #: 1994217

Contents

Basic Setup with eDART® Software	3	Remote Access & Viewing the eDART®	37
Start Machine	4	Remote Access	38
Create New Machine	5	Viewing the eDART®	38
Placing Sensors	6	Making the Connection	38
Configuring Sensors	7	Viewing the Current Process	40
Testing Inputs/Outputs	13	eDART® Process Setup	49
Modify Existing Machine	21	Select Existing Process	50
Choose Pre-Existing Mold	22	Create New Process	51
Create New Mold	23	Alarm Limits	53
Modify Existing Mold	24	Remove Alarm	55
Setup Process Overview	25	Adjust Alarm Levels Automatically	56
Job Overview	29	Adjust Alarm Levels Manually	57
Cycle Graph	31	Sorting Actions	58
Diagnostics	36	Control Settings	59

Contents *continued*

eDART® Overview Screen	61	eDART® Settings Button	92
Overview	62	eDART® Settings Button	93
Error Display	63	Manage Machines	94
Process Match Variable	64	Manage Molds/Setups	94
Cycle History	65	Configure eDART®	96
Options Tab	66	Networking Setup	97
Quality Sampling Tool	67	Serial Ports	99
Process Settings	68	eDART® Security	100
Velocity to Pressure Transfer Tool	69	Security	101
Saving Master Setup	72	Configure Groups	102
Add Note Tool	74	Configure Users	103
Cycle Graph	75	Change Password or Security Level	104
Cycle Graph	76	Log Files and Raw Data Viewer	105
Graph Control Menu Auto Scale Curves	78	Audit Log	106
Set Fill Volume at Cursor	78	Diagnostic Page	107
Set Volume Zero at Cursor	78	Raw Data Viewer	108
Adding Curves	79	Sensor Data Details	109
Template Controls	83		
Individual Curve Menu	84		
Summary Graph	86		
Summary Graph	87		
Auto Scale All Curves	88		
Add A Curve	88		
Remove All Curves	89		
Add Note at Cursor	90		
Individual Curve Configuration	91		



Basic Setup with eDART® Software

This section walks you through the setup for the software for the eDART®.

In This Chapter


- 4** Start Machine
- 5** Create New Machine
- 6** Placing Sensors
- 7** Configuring Sensors
- 13** Testing Inputs/Outputs
- 21** Modify Existing Machine
- 22** Choose Pre-Existing Mold
- 23** Create New Mold
- 24** Modify Existing Mold
- 25** Setup Process Overview
- 29** Job Overview
- 31** Cycle Graph
- 36** Diagnostics

Start Machine


The eDART® allows for many Machine, Mold, and Process setups to be stored in the memory for future runs. It is necessary to set up the Mold or Machine only once, the first time that it is started. Machine input, output configurations and the Machine size information are stored in the Machine file. Alarm Limits and diverter settings are stored in the Process folder.

Always choose the Machine name from the Drop-down menu if it already exists. Only create a new Machine after checking for an existing Machine setup.

Once a Machine is created there is no need to set it up again. The eDART® will remember all of the configurations for the machine. The Sequence Module is a Machine Identifier and will automatically select the Machine from the Machine Drop-down menu when connected to the system.



A: Click on the “Machines” Button on the eDART® Home Page.



B: If the Machine is in the list click on it to select.

C: If the Machine is not in the list click on “Create New Machine”.

D: The selected Machine will be highlighted and have a check mark beside the name.

If a Machine is selected from the drop-down menu the Machine Name will show on the Machine button.


Create New Machine

When Create New Machine is selected the eDART® will step through the Machine Creation Process. The first window will show the “Basic” tab. Do not use the Create new Machine Button if the Machine exists in the drop down menu. Instead, click on it to select.


Sensor Icon Legend

	LE-R-50 - Stroke Encoder
	Proximity Switch
	Hydraulic Sensor
	Pressure Sensor
	Analog Input
	OR2-M
	Delta Pressure Sensor
	ID-7
	Mold Deflection
	Temperature Sensor

Placing Sensors



- A:** Available Sensor List - Drag and drop sensors from the Available Sensor list into their correct locations. When a sensor is held over a location the window will open and allow correct placement of sensor within the location.
- B:** Drag the LE-R-50 or analog input modules connected for screw position into this box. See Position/Velocity section for details.
- C:** Drag the Hydraulic sensor or the analog input module connected for injection pressure into this box. See Injection Pressure section for details.
- D:** Drag any other Machine sensors that are connected to the Machine into this box.
- E:** When you connect the Sequence Module to the eDART® it will automatically assign it to the Sequence Signal area. See Sequence Module Config for more information.




All sensors attached to the system will automatically display in one of the Available Sensor lists.

The Sequence Module is a Machine Identifier for the eDART® system. After the initial setup for the Machine the eDART® will automatically display the Machine Name on the start page.

Configuring Sensors

Position/Velocity For LER-50


When the Position/Velocity sensor is placed over the Position/Velocity location on the machine, a window will open up to allow the sensors to be dropped into the correct location.



A: Drop the LE-R-50 sensor output 1 from the "Available Sensor" List into the Position location. Select the screw direction. (see Set Screw Direction)

B: The Velocity sensor will automatically assign.

Position/Velocity From Analog Input



A: Drag analog input connected to Position or Velocity into the correct locations.

B: Click on the "i" to get Analog Input scaling window Scale Analog Inputs for Position and Velocity.

Position/Velocity Analog Configuration

Enter the AI Position Module's Parameters

A Maximum Position:

B Voltage at Maximum Position:

C Voltage at 0 Position:

A: Enter the maximum shot size on the machine.

B: Run the screw to the maximum shot size, select “Set” to automatically set the maximum position voltage level.

C: Run the screw to bottom (0 cushion), select “Set” to automatically set the 0 position voltage level.

Enter the AI Velocity Module's Parameters


Maximum Velocity:

Voltage at Maximum Velocity:


Voltage at 0 Velocity:

Injection Pressure Hydraulic Sensor Configuration

Hydraulic Machines require a Hydraulic Pressure sensor.



- A:** Drag the Hydraulic sensor from the Available Sensor List to the Injection Pressure Location.
- B:** If the Machine has the Dynamic Braking option, drag that sensor into the Braking Pressure Location.
- C:** Click on the "i" to enter the Intensification Ratio window.



Injection Pressure Analog Configuration

Electric Machines Require an Analog Input Module to be wired to the Output for Injection Pressure from the Machine.

Pressure [X]

Injection Pressure

(A) SN: 0330000 231:1
Value: 12.62 p (i) (B)

Braking

A: Drag the Analog Input wired to the Injection Pressure Output to the Injection Pressure location.

B: Click on the “i” to get the scaling window.

Enter the AI Pressure Module's Parameters

(C) Maximum Pressure: 30000 PSI


(D) Voltage at maximum pressure: 10 v

(E) Voltage at 0 pressure: 0.0000 v

Cancel Save (F)

Sequence Module Configuration


Triggers or Machine Sequence signals are 24VDC on/off signals from the machines digital outputs. The *eDART*® uses these signals for timing. The sequence module will automatically assign itself to the Sequence signal box.



A: Click on the "i" to see the trigger lights and assign signals

Triggers tell the *eDART*® when to execute different functions like zeroing sensors, Starting Cycles, and calculating values, therefore, it is important that the triggers are labeled exactly what they are.

The required signals, Injection Forward, Screw Run and Mold Clamped are pre assigned to the sequence module and can't be changed.



Triggers that are connected but not Pre-Assigned need to be labeled.

ID7	
<input checked="" type="radio"/> Injection Forward 0504000233:1	Shuttle Position #A
<input type="radio"/> Not Assigned 0504000233:2	Shuttle Position #B
<input checked="" type="radio"/> Screw Run 0504000233:3	Shuttle Position #C
<input checked="" type="radio"/> Mold Clamped 0504000233:4	Semi-Auto or Auto
<input type="radio"/> Not Assigned 0504000233:5	Machine in Manual
<input type="radio"/> Not Assigned 0504000233:6	Mold Closing
<input type="radio"/> Not Assigned 0504000233:7	Mold Opening
<input type="radio"/> Not Assigned 0504000233:7	Mold Fully Open
<input type="radio"/> Not Assigned 0504000233:7	Second Stage
<input type="radio"/> Not Assigned 0504000233:7	First Stage

Cancel **Save**

B: Click the terminal location to assign the trigger name.


C: Click on the correct label for the trigger connected to the terminal.

D: To unassign a previously selected trigger, click on the terminal and change it to “Not Assigned”.

It is extremely important to label the triggers correctly. Leave them as “Not Assigned” if you are unsure.

Testing Inputs/Outputs

When all sensors have been assigned, and the “Next” Button is clicked, the eDART® will automatically take you to the Test Inputs Screen.



A: To verify triggers, watch the lights to make sure that the triggers come on and off at the correct times.

The Picture is an animation of your Machine and should move with the machine as a visual aid in Trigger assignment.


If the trigger light does not light up, label that input terminal not used or correct wiring to module.

If the trigger lights up at the wrong times, label that input terminal not used or correct wiring to module. You must go back to the Inputs page to makes changes.

B: Click on this button to set the direction of the screw. See Set Screw Direction for details.

C: Click this button to zero the injection pressure. See Zero Injection Pressure for details.

Set Screw Direction




A: Select option that matches the stroke sensor cable direction.

B: Bottom the screw and select, to set the screw bottom position.

Zero Injection Pressure

This needs to be completed while the machine is not injecting.



A: Select "Set To Zero" to set the Zero (0) while the machine is idle.

Automatic Trigger Testing

This window will appear after completing the Test Input page. If the triggers are incorrect during the cycle, an error message will appear once the job has started.

Following errors have been encountered:

Not Assigned

No signal has been received This input is not used **A**

Mold Clamped

No signal has been received This input is not used

Screw Run

No signal has been received This input is not used

Injection Forward

C **CANCEL** **B** **OK**


A: Click on the “This input is not used” box if the trigger is not working or incorrect.

B: Select “OK” to proceed without correcting the errors.

C: Select “Cancel” to return to the test inputs page to correct the errors.

Configure Outputs


Use the eDART® Outputs page to assign the output modules wired to machine.



- A:** Available Sensor List - Drag Output Modules from the Available sensor list into the location where they are wired.
- B:** If a module is attached to the Robot or Part Diverter drop it into the Sorting box. See Sorting for details.
- C:** If a module is wired to V>P transfer of the machine drop it into the Controls box. See Control Velocity to Pressure Transfer for details.


Sorting

When a Sensor from the Available Sensor list is held over the Sorting box, the window will open so that the sensors can be dropped into their positions.



A: Click on the “i” to configure the sorting output.

Sorting cont.



Shot Containment:

If the entire shot is to be segregated for inspection you will need one side of an OR2 module wired to Robot or Diverter. There will be only one OR2 module entry in the Sorting box. Click on the “i” and choose “Failsafe Good Part Output”.


Individual Cavity Containment:

If individual cavities are to be segregated you will need one side of an OR2 Module for each cavity. Drag all of the OR2 entries into the Sorting box. Click the “i” and choose “Individual Cavity Sorting” for each module.


The cavity identification for each module will be set in the Mold setup screen.

Control Velocity to Pressure Transfer

When you hold a sensor over the Control box, the window will open so that all of the control sensors can be added to control list.




- A:** Drop all of the Modules wired to controls into the Controls box.
- B:** Click on the “i” button to set up the control output type for each module.
- C:** Choose the desired setting from the drop down.



Output Testing

Use the Test output page to insure that the outputs work as expected.




A: Click on the Test button to test each output.

B: Check that the light turns green.

C: Check that the LED on the output module turns green. Check that the device alternates correctly on the machine, robot, etc.

Summary Tab


This tab shows the type, location and serial number of all sensors relating to this machine, whether they are in use or not. Click 'Finish' to continue.



Modify Existing Machine




A: Click on the “Machine” button.



B: Click on the arrow beside the Machine Name to get to the Machine Setup window.

Choose Pre-Existing Mold

When a Mold is created the eDART® will store the mold information. It is not necessary to set the Mold up again. Instead, just select it from the Mold Drop-down menu.




A: Click on the “Mold” Button.

B: Click on the correct Mold to Select.

Create New Mold


Do not use the “Create New Mold” button if the Mold has been set up previously. Instead select it from the drop-down menu.




A: Click on the “Mold” Button to get the Mold Menu.

B: Click on the “Create New Mold” Button.

When “Create New Mold” button is selected the Mold Setup window will appear.




Modify Existing Mold



A: To modify an existing mold, click on the “Mold” button.

B: Click on the arrow next to the Mold that needs to be edited.


C: Go to the appropriate tab or field to make the required edits. Click “Next” until the last screen is reached. Click ‘Finish’ to continue.



Setup Process Overview

Setup



Use this to create a new setup or if something has changed in a saved process that will affect alarm settings or the timing of the part segregation device. Saving a setup for the new process allows you to get back to the old process at a later time if necessary. (Refer to the Process Setup Manual for more details)



A: Click on the “Setup” button from the Home Page of the eDART®.

B: Click on the “Create New Process Button”.

Basic Setup



When “Create New Process” is selected, the “Basic” process setup screen will appear.

A: Enter the Process Name.


B: Enter the Standard Cycle Time for this process

Alarm Limits

Click on the “Next” button to go to the “Alarm Limits” tab (refer to the Process Setup Manual for more details).

This configuration will include the addition of Process Alarms/Warnings and Part Diverter/Robot Signal Controls.

When a process alarm or warning is added, the eDART® will display both a low and high alarm. These alarm levels can be set either automatically or manually based on actual part characteristics.



- A:** Click on the “Add Alarm” Button. When “Add Alarm” Button is selected the eDART® will display the list of available alarms.
- B:** Choose the positions you wish to monitor or alarm
- C:** Click “Done” to apply Warnings and Alarms when complete

Sorting Actions

Click the “Next” button to display the “Sorting Actions” Window. This window will allow for input on how to treat the sorting output signal to insure the parts reach their proper destination. (Refer to the Process Setup Manual for more details)

The screenshot shows the 'Sorting Actions' window in the software interface. The window is titled 'Process Setup Step 3 of 4' and has tabs for 'BASIC', 'ALARM LIMITS', 'SORTING ACTIONS', and 'CONTROL SETTINGS'. The 'SORTING ACTIONS' tab is active, showing 'Sort Settings' with the subtitle 'Set timing and options for part segregation'. Under 'Diverter Timing Controls', there are four options: A (checked), B (unchecked), C (unchecked), and D (unchecked). Option A is 'Hold diverter position until alarm changes'. Option B is 'Hold diverter position' with a value of 2.00 seconds. Option C is 'Reject' with a value of 1 shot(s). Option D is 'Delay diverter outputs for' with a value of 1 cycle(s). There is a 'CLEAR DELAYED DIVERTER OUTPUTS' button below the options. At the bottom, there are 'BACK', 'UNDO', 'CANCEL', and 'NEXT' buttons.

- A:** Check this box to hold the part diverter in one position until there is a change in the alarm state.
- B:** Check this box and enter the amount of time for the contact to be held closed when a good part signal is generated.
- C:** To use the “Reject After Down” feature, check this box and enter number of parts to be rejected after the Machine has been down.
- D:** To use the “Diverter Delay” feature, check this box and enter the number of cycles that you would like to delay the output. Use this feature for conveyers that have many parts on it before the diverter device or over-mold processes that have alarms set on the 1st shot.

Control Settings

This page allows the user to configure how alarms are calculated. It also contains the settings for additional control output configurations. This page allows for the modification of Integration limits and for configuration so that you can see a temperature drop instead of temperature rise in LSR or other thermo-set materials. (Refer to the Process Setup Manual for more details)

A: Click here for more control options.

B: Click on “Less” to hide them.

C: Click on “Finish” to complete the process setup and go back to the main window.

Start Job


Once you have set up the machine, the mold, and the process as seen in the previous pages, you are ready to start your job.



A: To Start the process, click on the “Begin” button at the bottom of the screen.

Job Overview

At the top of the Overview page are four ‘buttons’. These allow you to navigate between the screens. You can click on each button or use the arrows to go back and forth as well.



A: Job Overview: At a glance basic information


B: Cycle and Summary Graphs

C: Job Audit page

D: Diagnostics page

Job Overview, continued


On this screen you will see:



- A: Machine Status
- B: Machine, Material and Mold Match status indicator
- C: Software Tools and Options
- D: Good / Bad Part Counts and 100 shot history


Cycle and Summary Graph View

- A: Cycle Graph
- B: Summary Graph




Cycle Graph

The Cycle Graph is where the real time data is displayed visually. All active sensors will be available to view in the graphical real time form.




- A:** Main Graph Area. All real time graphs will be displayed in this area.
- B:** Curve Help Screen. This screen shows sample curves and gives descriptions of important features of each curve.
- C:** Time span visible on the graph. These values can be changed to show any portion of the graph in detail.
- D:** Digital input-output graph area. Any on/off signals can be displayed in this portion of the graph. These signals would include triggers, control outputs, and sorting outputs.
- E:** Click this button to maximize or minimize the graph.
- F:** Use the plus and minus signs to zoom in and out. The graph will always start from 0 seconds as you zoom.

Cycle Graph cont.



- G:** Click this button to overlay all future cycles on the display.
- H:** Cursor. The cursor can be placed on the graph to view values for curves at specific times.
- I:** Time into the cycle will be displayed at the top of the cursor.
- J:** Time Date Stamp for the present shot is displayed here. All shots are differentiated with a time date stamp.
- K:** Each Curve displayed on the Cycle Graph will have a Curve Identification button. The Curve name will be displayed on the button and will be the color of the curve.

Graph Control Menu Auto Scale Curves




A: Click on the “Graph Controls” Menu.

B: Click on “Auto Scale” from the menu. The curves will automatically scale fit the screen.

Set Fill Volume at Cursor

The *eDART*® uses the area under the fill portion of the Injection Curve as an Effective Viscosity Measurement as the area varies directly with variation in viscosity. This value is correct only when calculated during the dynamic fill portion of the cycle. To insure that this is calculated at an appropriate place, the volume at transfer needs to be entered into the *eDART*®.




A: Place the Cursor at transfer on the Cycle Graph.

B: Click on the “Graph Controls” Menu.


C: Click on “Set Fill Volume at Cursor”. The *eDART*® will use the volume measurement at that point as an ending point for the Effective Viscosity Measurements.

Cycle Graph Values

A: To see numerical values for curves on the Cycle Graph, click your cursor on Summary Data Table, select the settings gear, and check the boxes for the values you wish to see, and click Apply.



B: When 4 or more sensors are present, a bar graph can be obtained by clicking Summary Bar Chart to view the desired curve.



Audit Log

MENULOGIN

◀○○●○▶
Audit Log

HELPRJG CHATSETTINGS

Date/Time ▼	Activity	User	Detail
2014/05/08 07:08:28	Sensor 09 021 00963:1: piezo_type	Admin	Piezo Adapter
2014/05/08 07:08:28	Sensor 09 021 00961:1: piezo_type	Admin	Piezo Adapter
2014/05/08 07:08:18	Job Started	Admin	Arburg
2014/05/08 07:06:03	Saved Mold Setup	Admin	V10 test mold
2014/05/01 14:15:04	Job Stopped.	Admin	
2014/05/01 14:14:55	Sensor 09 021 00961:1: piezo_type	Admin	Piezo Adapter
2014/05/01 14:14:44	Job Started	Admin	Arburg
2014/05/01 14:14:39	Saved Mold Setup	Admin	V10 test mold
2014/05/01 14:11:38	Job Stopped.	Admin	

A: Sort by Date, Activity or User to see what changes have been made over a period of time, and who made them.

Diagnostics

	Serial # ▲	Attached to	Sensor Type	Location	Status
●			Diagnostic Info	Port 1	Ok
●			Diagnostic Info	Port 2	Ok
▲	0123600123:1	Mold	Ejector Pin Force	End of Cavity #1;A	Valid
▲	0407500037:1	Machine	Control Output	V->P Transfer	Valid
●	0407500037:2	Machine	Sorting Output	Reject Control	Valid
●	0460000136:1	Machine	Stroke	Injection	Valid
●	0460000136:2	Machine	Velocity	Injection	Valid
▲	0504000261:1	Machine	Seq. Module Input	Injection Forward	Valid
▲	0504000261:3	Machine	Seq. Module Input	Screw Run	Valid
▲	0504000261:4	Machine	Seq. Module Input	Mold Clamped	Valid

A: Click on the arrow or the fourth dot to get to the diagnostic page.

B: Click on the triangle to display information about sensor status.

Sensor Status 0123600123:1 End of Cavity #1;A ✕

Preload

Zero Offset

Sensor Calibration

Preload should be Green.
 If Preload is Yellow or Red, check the sensor pocket bore for proper depth. Pocket corners need to be sharp, remove any radius.

Zero Offset should be Green.
 If the sensor is Yellow, the sensor is most likely functional but should be calibrated at your convenience. If the sensor is Red, the sensor is no longer functional. Return the sensor to RJG for Recalibration.

C

C: Click on the “View Raw Data” button to display more detailed information about the sensor.



Remote Access & Viewing the eDART®

This section describes the options for remote access and viewing of the eDART®.

In This Chapter

- 38** Remote Access
- 38** Viewing the eDART®
- 38** Making the Connection
- 40** Viewing the Current Process

Remote Access

Viewing the eDART®

First, it is important to establish what you want to do with your system. In general, you will want to do one of the following:

- View the Current Process (in real-time)
- Copy/Move Data, Templates, etc.
- Analyze Data

Before you can do any of these things, you will need to make a physical connection from the eDART® to a remote computer. The options for remote viewing are listed and described below. RJG strongly recommends utilizing an Ethernet connection because of its speed and ease of use.

NOTE

Installation of eDART™ System Utilities Software is required

Making the Connection

Ethernet (preferred method)

An Ethernet connection links the eDART® to another computer or a network so that information can be transmitted between them. See the “Making the Connection” section for detailed instructions on making the Ethernet Connection.

- Network: An eDART® can be wired into an office network using a hub.
- Cross Over Cable: Allows a computer to communicate with an eDART® directly without using a hub.

For instructions on making a connection using a modem, see the “Making the Connection” section for details.

After you make a physical connection to the eDART®, you can choose what you would like to do:

1. Analyze Data

Use the Analyzer program to view saved eDART® data. Refer to the Analyzer section of this chapter for more information.

2. Copy/Move Data, Templates, etc.

Use the “Filezilla” program to copy or move eDART® data, templates, or other files to an office computer, server, or other location so that the information can be emailed, burned to disk, etc. Refer to later section for Filezilla FTP program information.

3. View Current Process

Viewing the current process in real-time requires a Phindows license for each remote computer you are using for viewing.

4. Update Your eDART® Software

You can perform an eDART® software update using either a serial or Ethernet connection.

NOTE

The computer must have a network card installed.

Ethernet Connection

Network

To wire the *eDART*® into your existing network, connect the Ethernet cable to the RJ-45 Ethernet port on the *eDART*®. Connect the other end of the Ethernet cable to the hub.

Crossover Cable

To wire the *eDART*® directly to another computer (without a hub), connect one end of the Ethernet crossover cable to the RJ-45 Ethernet port on the *eDART*®. Connect the other end of the cable to the computer's network jack.

Your computer will need a fixed IP address. You can also set the IP address of the *eDART*® to match your network. Select "Configure *eDART*" from the QNX icon on the *eDART*® toolbar. This will prevent issues involving changing the IP address each time the computer is moved. For more information, refer to the "Configure *eDART*®" section of the Helpviewer.



You must stop Phindows before disconnecting the Ethernet crossover cable.

Viewing the Current Process

Phindows

The Phindows program allows users on remote Windows platforms to connect to and interact with applications running on a QNX computer (e.g. *eDART*®).


You can view the software remotely at as many workstations as desired. You will, however, need a separate Phindows license for each workstation. Phindows is an optional piece of software for the *eDART*® system.

Installation

1. Select “Run” from the Start menu
2. Type “A:\setup.exe”
3. Click OK.

You can also create a Phindows shortcut for each *eDART*®.

1. Use Windows Explorer to find Phindows.exe in C:\Program Files\RJG Insight System\Photon\phindows.exe.
2. Right click on Phindows.exe
3. Select “Create Shortcut”
4. Right click on the shortcut and select Properties from the menu.
5. Click on the Shortcut tab.
6. Modify the Target to read: C:\Program Files\RJG Insight System\Photon\phindows.exe -t (IP Address) -n (Node number) -u -o1.
7. Click OK to save the changes
8. Verify that the *eDART*® is attached to the network
9. Double click the shortcut to run the program




eDART® Locator

eDART® Locator is part of the *eDART*® System Utilities Software CD. It is used in conjunction with Phindows to view *eDART*s from a Windows computer.

- Double click the *eDART*® Locator option inside the RJG Insight System folder on the desktop.
- First, choose File, Settings. Use the browser (...) button to choose the path to Phindows.
- When finished, click OK.

Next, find the *eDART*s under the Machine Name heading. Double click the desired name to view the software for that *eDART*®.



Machine Name	Net Group	System Type	Connection Info
Plant/Cell/Machine	Your Group	eDART #101	192.168.1.101#5731
Plant/Cell/Machine	Your Group	eDART #205	192.168.1.205#5731
Plant/Cell/Machine	Your Group	eDART #106	192.168.1.106#5731
Plant/Cell/Machine	Your Group	eDART #150	192.168.1.150#5731
Plant/Cell/Machine	Your Group	eDART #108	192.168.1.108#5731
Plant/Cell/Machine	Your Group	eDART #204	192.168.1.204#5731
Plant/Cell/Machine	Your Group	eDART #102	192.168.1.102#5731
Plant/Cell/Machine	Your Group	eDART #206	192.168.1.206#5731

Push to Start

If *eDART*® names do not appear, you will have to add the IP addresses to a list file.

Inside the RJG Insight System folder there is an “Edit *eDART* IP List” option. Double click on this option to open the file.


- Type in the IP address of the first *eDART*®.
- Click Enter and then type the next IP address.
- Choose File, Save and then close.
- Re-open *eDART*® Locator.

FTP File Transfer

To transfer data from an eDART® to another PC, laptop, or server, access the Filezilla program from your “RJG Insight System” folder. You should see the screen below:

NOTE

Installation of eDART™ System Utilities Software is required.



1. Address: Type in the IP address of the eDART® or computer you would like to connect to. If you are using a serial connection, type in “10.0.0.1”.
- 2.
3. User: Type in “root”. Use lowercase letters.
- 4.
5. Password: Type in “evintea”. Use lowercase letters.
- 6.
7. Quickconnect: Click this button to connect to the IP Address you’ve specified.
- 8.
9. Local Site: By clicking on the “+” and “-” boxes, select the directory location you would like the transferred data to be placed.
- 10.
11. Remote Site: Select the “e-dart” folder and then select the “data” folder. From the list of data, select the file(s) you would like to transfer by clicking the name once to highlight it.
- 12.
7. Once highlighted, hold down the left mouse button and drag the file here. Repeat for each file to be transferred. When all files have been selected, right-click anywhere in this box to bring up a menu. From the menu, select “Process Queue”. The file(s) will be transferred to the Local Site you’ve selected.

NOTE

Clicking on the folder followed by two dots takes you up one level.

Once installed, the Filezilla program contains detailed help.

Analyzer


The Analyzer is a Windows application for use with RJG's DART*Vision*™ or Insight System™. Follow the instructions below to use the Analyzer tool.

Scan Network for eDARTS

1. Launch the Analyzer

The main screen of the Analyzer is the data selector. The Data Directory at the left side of the screen lists directories where data has been saved (by mold).

At the bottom of the screen is a toolbar where you can select various tools for the viewing, analysis, or calculation of data.



2. Select a folder

In the Data Directory, click on the folder with the name of the mold data you would like to view. If you want to choose a specific set of data from the folder, click the "+" to the left of the folder. This will expand the directory and give more specific options.

NOTE

If the folder is labeled "L", it contains local data (data from the directory you chose above). If the folder is labeled "ED", that data is from an eDART® on the network.

3. Select Start and End Date

The two calendars on the right side of the screen allow you to choose a start date and end date for the data you have chosen to view. If the background color is gray, there is no data available to display. If it is white, data is available. The dates marked with bold text indicate dates where data exists. Using the calendar on the left, select the starting date for the data you would like to view. Using the calendar on the right, select the ending date. You can also select data starting and ending times below the calendars.

(View the Current Process continued)


4. Select an Application

From the toolbar at the bottom of the screen, choose the application that you would like to use with your selected data range.



Summary Graph

The Summary Graph provides a graphical display of summary values allowing you to view trends. Multiple summary value trends can be displayed here at one time. A summary value is a single number (data point) for each cycle; i.e. peak cycle integral, cycle time, etc.



Title Bars

Displayed at the left side of the screen, these bars indicate which summary measurements are being shown on the graph. To add a measurement to the summary graph, choose "Add Curve" from the Graph Controls menu or click on the title bar and press the Add Curve button.

Cursor

The cursor is the vertical line on the graph. It can be moved on the graph by left clicking on the point you want the cursor to move to or left click and drag the cursor itself. The numerical values for each data point are displayed underneath the title bars.

Get Cycle

The Get Cycle button at the bottom of the screen will bring up the cycle graph for the data selected by the cursor.

(View the Current Process continued)

Export

Press this button to export the data on the summary graph to an Excel spreadsheet. To select only a certain area of the summary graph to export, zoom in on that area (right click and drag) and then press the Export button.

Note


To add a note, place the cursor on the desired data point and choose Add Note from the Graph Controls menu. The note will appear as a small icon at the bottom of the graph. To view the note, simply click on its icon. To change the note, choose Edit Note from the Graph Controls menu.

Zoom/Unzoom

To zoom in on a particular area of a curve, choose Zoom from the Graph Controls menu or right click and drag on the desired area of the graph.

Cycle Graph

The Cycle Graph displays saved cycle data, one shot at a time.



Overlays

You can view multiple shots at a time by turning the Overlays function on (Press the OV button at the bottom of the screen).

Zoom

To zoom in on a particular area of a curve, choose Zoom from the Graph Controls menu or right click and drag on the desired area of the graph.

Cursor

The vertical cursor on the graph displays the numerical values for each curve. It can be moved on the graph by left clicking on the point you want the cursor to move to or left click and drag the cursor itself.

(Cycle Graph continued)

Add a Curve

To add a curve that is not displayed, select Add Curve from the Graph Controls pull-down menu.

Data Replay


You can scroll through data using the arrows at the bottom of the screen. The shot time stamp indicates the date and time each specific shot was made. You can replay the data by pressing the green button at the bottom of the screen. Set the replay speed using the slider to the left. As the cycles replay, the cursor will move on the summary graph (if both screens are visible) so you can see which cycle data corresponds to the summary data. The red button will stop replay.

Save as Template

To use the cycle data on the graph as a template to compare other cycles against, select "Save as Template" from the Graph Controls menu. Type in a description of the template and press Save. The template can be modified in the Template Controls selection. These templates are readable by the eDART®.

Statistics Screen

The Statistics screen will calculate average, standard deviation, etc. for the data range displayed on the summary screen.



Adding/Removing Values

To add additional values, press Add. Choose the calculation (Average, Maximum, Minimum, Standard Deviation, etc.) you would like to apply to the selected data range and press OK. Select a summary measurement and location from the list that you would like to view and press OK. Repeat to add additional measurements. To remove a measurement that had already been added, highlight it and press Remove.


(Cycle Graph continued)

Data Range

Choose a view (Summary View, Shots Back, or Whole View) from the Data Range combo box at the top of the screen. If you select Shots Back, you can indicate the number of shots.

Part Measurement


The Part Measurements tool is used with the Part Sampling tool in the eDART® software. Using the Part Sampling tool, you can collect samples for later analysis by marking the datapoints where you took these. In the Part Measurements tool, you can enter part measurements.



	Group Name	Shot D/T	Length	Part Weight	Surface Finish
-	Test 1	01/01/2002 19:28:45			
		19:28:45	1.000	1.000	25.00
		19:29:15	2.000	1.000	26.00
		19:29:45	3.000	1.000	24.00
		19:30:14	2.000	1.000	25.00
		19:30:44	3.000	1.000	25.12
+	Test 4	01/01/2002 19:33:29			
+	Test 6	01/01/2002 19:38:00			
+	Test 8	01/01/2002 19:44:28			
+	Test 10	01/01/2002 19:48:44			

Data Export

The Data Export tool allows you to choose summary measurements and export them to a csv (Excel readable) file where additional data analysis can be done. This tool can also be accessed from the summary graph.



Column #	Export Measurement
1	Shot Time Stamp
2	Average Value, Fill Speed (FillSp)
3	Gate Seal, Post Gate (PSTgsl)

(Cycle Graph continued)

Adding/Removing Summary Measurements

Press Add and select a summary measurement and location from the list that you would like to view and press OK. The measurement header will appear at the end of the list.

To insert a measurement in a specific place in the list, highlight the measurement header directly below where you would like the new measurement to appear. Press Insert and select a summary measurement and location from the list. The measurement headers can also be moved around by clicking and dragging.

To remove a measurement that has already been added, highlight the header and press Remove.

Save Config

Saves the specific measurement names. This is useful if you frequently export a particular format.

Include Measurement Headers


Check this box if you would like the measurement headers to be exported along with the data.

Only Export those Shots with Part Measurement Entries

Check this box if you would like to only export the Part Measurement data.

When finished, press *Export*.

NOTE
***Data Export works with
summary data only.***



eDART® Process Setup


This section describes how to set up a process on your eDART® by using either an existing process or by creating a new process.

In This Chapter

- 50** Select Existing Process
- 51** Create New Process
- 53** Alarm Limits
- 55** Remove Alarm
- 56** Adjust Alarm Levels Automatically
- 57** Adjust Alarm Levels Manually
- 58** Sorting Actions
- 59** Control Settings

Select Existing Process

If you have a process setup from a previous run, simply select it from the list. The eDART® will remember saved setups from previous runs. It is not necessary to enter a new process when you restart a job.




A: Click on the “Setup” Button.

B: Click on the Process that you would like to run.

C: Click the “Begin” button when Machine, Mold, and Process are selected.

Create New Process

Only create new setup if something has changed in your process that will affect alarm settings or the timing of the part segregation device. Saving a new setup for the new process allows you to get back to the old process at a later time if necessary.



A: Click on the “Setup” button from the Home Page of the eDART®.

B: Click on the “Create New Process Button”.

Create New Process con't.

When “Create New Process” is selected, the Basic Process setup screen will appear.


- A:** Enter the Process Name.
- B:** Enter the Standard Cycle Time for this process
- C:** Enter any notes about the process
- D:** Click on 'NEXT' to go to the next page

Alarm Limits


When the “Next” button is selected the “Alarm Limits” tab will open to allow for process configuration.

This configuration will include the addition of Process Alarms/Warnings and Part Diverter/Robot Signal Controls.

When a process alarm or warning is added, the eDART® will display both a low and high alarm. These alarm levels can be set either automatically or manually based on actual part characteristics.






A: Click on the “Add Alarm” Button. When “Add Alarm” Button is selected the eDART® will display the list of available alarms. All values will show “Invalid” until the process is actually running.



The same screen can be accessed from within a running process using the Options Menu.

Alarm Limits cont.



A: Click on the button that represents the type of alarm to be added.

Machine alarms include any machine based variable the eDART® can calculate. Fill Time, Cycle Time, etc...

Mold alarms include Average Value of Center or Front Barrel Temperature and Feed Throat Temperature.

Material alarms would include changes to the material, Effective Viscosity, Screw Recovery, etc...

B: Click on the Alarm type from the list. If there are more than one variable of that type the eDART® will display the location choices to the right of the type.

C: Choose the desired location from this area.

D: Click on this icon to toggle between alarm types: Alarm, Warning, Alarm and Warning.

Hold Time		No Alarm
Shot Stroke		Warning Alarm
Cycle Time		Reject Alarm
Fill Speed		Reject and Warning Alarm

Remove Alarm

All alarms added to the process will be displayed on the “Alarm Limits” tab. From this tab you can edit the levels for your alarms both manually and automatically and remove alarms

	Cycle Name	Type	Value	Low	High	Units
<input checked="" type="checkbox"/>	Average Value:End of Cavity Cycle Integral	Alarm	Invalid	23271	23487	%
<input type="checkbox"/>	Average Value:End of Cavity Cycle Integral	Warning	Invalid	23295	23463	%
<input checked="" type="checkbox"/>	Fill Speed	Alarm	Invalid	26.00	28.50	in/sec.
<input type="checkbox"/>	Fill Speed	Warning	Invalid	27.00	29.00	in/sec.
<input checked="" type="checkbox"/>	Cycle Integral:Injection Pressure	Alarm	Invalid	3199	3205	psi-s
<input type="checkbox"/>	Cycle Integral:Injection Pressure	Warning	Invalid	3200	3205	psi-s

A: Click on the check box next to the alarm to be removed.

B: Click on the “Remove Alarm” button.

Adjust Alarm Levels Automatically

Once Process Alarms are added, use the Alarm Limits page to adjust the limit levels. This can be done automatically or manually based on the part characteristics.

Process Setup Step 2 of 4

Alarm Limit Settings
Choose Alarm variables and set upper and lower limits

	Cycle Name	Type	Value	Low	High	Units
<input checked="" type="checkbox"/>	Average Value:End of Cavity Cycle Integral	Alarm	Invalid	23271	23487	%
<input type="checkbox"/>	Average Value:End of Cavity Cycle Integral	Warning	Invalid	23295	23463	%
<input checked="" type="checkbox"/>	Fill Speed	Alarm	Invalid	26.00	29.50	in/sec.
<input type="checkbox"/>	Fill Speed	Warning	Invalid	27.00	29.00	in/sec.
<input checked="" type="checkbox"/>	Cycle Integral:Injection Pressure	Alarm	Invalid	3199	3205	psi-s
<input type="checkbox"/>	Cycle Integral:Injection Pressure	Warning	Invalid	3200	3205	psi-s

Suggested Alarm Levels

C 4.50 above or below average for reject alarms

3.50 above or below average for warning alarms

D 20.00 Shot back for sigma
 Hour
 Min
 Shot

E SET

F NEXT

A: Click on the check box for each variable alarm that you want to adjust automatically.

B: Click on the “Auto-Set” button.

C: Enter the desired statistical level for the alarms selected to be adjusted.

D: Enter the number of shots to use for the level adjustment.

E: Click on the “Set button”.

F: Click on the “Next” button on the main Alarm Limit page.

Adjust Alarm Levels Manually


Most plastic parts have a very specific set of criteria that needs to meet to be considered a Good Part. The most accurate way to set alarms in the eDART® is based on in-cavity variables and actual part dimensions. The eDART® system has many tools to aid in the selection of these alarm variables. Once the alarm variables are identified, a simple high-low study can be executed to determine the correct alarm level based on part measurements. Always pull the levels in some to insure the alarms are conservative.

	Cycle Name	Type	Value	Low	High	Units
<input type="checkbox"/>	Fill Speed	Warning	Invalid	27.00	29.00	in/sec.
<input type="checkbox"/>	Cycle Integral:Injection Pressure	Alarm	Invalid	3199	3205	psi-s
<input type="checkbox"/>	Cycle Integral:Injection Pressure	Warning	Invalid	3200	3205	psi-s
<input type="checkbox"/>	Cycle Time	Alarm	Invalid	19.00	23.50	kgf/cm²-s
<input type="checkbox"/>	Fill Time	Alarm	Invalid	0.2758	0.2987	MPa-s
<input type="checkbox"/>	Fill Time	Warning	Invalid	0.2783	0.2962	Pa-s

- A: Enter the value for the Low alarm in this box. Parts with a value below this level should be too small or short.
- B: Enter the value for the High alarm in this box. Parts with a value above this level should be dimensionally too big.
- C: Use the drop-down menu to choose the units in which the values are to be displayed.
- D: When all alarms have been added and the levels have been set, click on the “Next” button to continue to the next portion of the set-up.

Sorting Actions

When the “Next” button is selected the eDART® will display the “Sorting Actions” Window. This window will allow for input on how to treat the sorting output signal to insure the parts reach their proper destination.




- A: Check this box to hold the part diverter in one position until there is a change in the alarm state.
- B: Check this box and enter the amount of time for the contact to be held closed when a good part signal is generated.
- C: To use the “Reject After Down” feature, check this box and enter number of parts to be rejected after the Machine has been down.
- D: To use the “Diverter Delay” feature, check this box and enter the number of cycles that you would like to delay the output. Use this feature for conveyers that have many parts on it before the diverter device or over-mold processes that have alarms set on the 1st shot.

Control Settings

This page allows the user to configure how alarms are calculated. It also contains the settings for additional control output configurations. This page allows for the modification of Integration limits and for configuration so that you can see a temperature drop instead of temperature rise in LSR or other thermo-set materials.

Computations Tab



- A:** Click on the “Computations” tab.
- B:** The value that you enter here will set the pressure at which the *eDART*® stops calculating Cavity Fill time.
- C:** Click on the drop down menu to choose the sensor to be used for Cavity fill time calculations. The *eDART*® default is set to 1000 PSI at the End of Cavity. This value is valid for most thermoplastics.
- D:** Click on the drop down menu to choose the Integration Limit. This is the place where the Cycle Integrals calculation ends. This is where the *eDART*® calculates the value and sends out the Good Part/ Bad Part signal to the part segregation device.
- E:** For a complete list of options click on “More”.

Screw Run End: Most Robots look for a Good Part/ Bad Part signal at this time.

Injection Start: If the robot or part segregation device needs to see the signal at a different time use Injection Start and put the end time in the Integration Limit Offset Time.

Mold Clamped End: This setting will capture the integral for the entire cycle, but the Good Part/ Bad Part Signal output will be too late for most robots.

Control Settings cont.

Integration Settings

Computations

Excessive Rejects

Consider cavity full when plastic pressure reaches 1000 psi at End of Cavity

End of cavity pressure integrals and compute alarm outputs at:

Integration Limit End: Screw Run End

Peak Computation Option: Integration Limit **A**

Start of Injection + x seconds 10.00 **B**

Injection Forward delay after M 0.00

Falling Temperature Detection **C**

[Less](#)

A: Click on the drop down menu to choose the time that the *eDART*® looks for Peaks within the cycle.

Integration Limit – the *eDART*® will look for peak pressures at the Integration Limit set in step 3.
End of Injection – the *eDART*® will calculate peak pressures at the end of hold.

B: If using the "Injection Start" option for the Integration Limit, enter the Integration limit time here.

C: Click on this check box if monitoring thermo-set materials like LSR.



eDART® Overview Screen


This section describes the features found in the eDART® Overview Screen

In This Chapter

- 62** Overview
- 63** Error Display
- 64** Process Match Variable
- 65** Cycle History
- 66** Options Tab
- 67** Quality Sampling Tool
- 68** Process Settings
- 69** Velocity to Pressure Transfer Tool
- 72** Saving Master Setup
- 74** Add Note Tool

Overview


After the Mold, Machine and Process is selected on the Job setup screen and the job is started, this screen will appear. From this screen you can navigate to any part of the eDART® including the setup screens if the job is stopped.



- A: This information bar will show any errors that the eDART® can identify. Click on “Dismiss” to remove warning.
- B: Click on this arrow to display all error messages.
- C: Options tab will allow access of tools like the Part Sampling tool and the Velocity to Pressure Transfer tool along with setup options, summary note entry screen, and save new setup screen.
- D: Stop the job using this button.
- E: This tab displays the Process Match status. Details about the Mold, Machine, and Material matches are available.
- F: Animation of press functions. The animation will move with the machine and process.
- G: The green and red boxes at the bottom of the screen will indicate your part count. Number of good parts will show in the green area and number of reject parts will show in the red area.
- H: Cycle Alarm note. For each reject cycle a note will be displayed showing which variable limit was exceeded.
- I: Cycle history. This will display the alarm state for each of the last 100 shots.

Error Display

The eDART® will display error messages at the top of the screen.



A: Check this bar to see error messages.

B: Click on this arrow to display more error messages. When the arrow is selected the error message window will expand to show more messages.

C: Click on “Dismiss” to remove each warning.

Process Match Variable

The Process Match is determined by the alarm and warning limits that have been set on key variables.

Machine: test/test/test Mold: Merry Christmas 2 Setup: Merry Christmas 3

Machine Cycle

Touch for Cycle Graph

A Stability

STOB JOB

Options

Touch for Cycle Graph

B Machine Match Material Match Mold Match

STOB JOB

Machine Match Values		
Cycle	Value	Template Value
Sequence Time:ScrewR	3.6770 sec.	3.7990 sec.
Sequence Time:MldC	5.8490 sec.	5.8480 sec.
Sequence Time:Cycle Time	18.0560 sec.	17.5500 sec.
Sequence Time:Fill Time	0.1510 sec.	0.2750 sec.
Average Value:Stable Hold	3962.7275 psi	104.8083 psi
Average Value:Fill Speed	3.4315 in/sec.	2.5108 in/sec.
Average Value:Back Pressi	608.7394 psi	4.7141 psi
Peak:Shot Stroke	0.6766 in	0.6741 in
Sequence Time:Hold Time	0.0050 sec.	0.0030 sec.

C


A: Displays green, red or yellow based on the Process Match. Click on the “Stability” tab to access the template match values.

B: Click on the button for the Process Match information you wish to access.

C: You can look at the template match numbers for the Mold, Machine or the Material values that have exceeded the alarm will highlight in red or yellow. Mold match will open the graphics screens.

Cycle History



The Cycle history for the last 100 shots will be displayed at the bottom of the Main eDART® screen. Good shots will show as green and Reject shots will show in red. Part counts for both good and reject shots will also be displayed for the whole run.



- A:** Reject Parts count
- B:** Good Parts count
- C:** Visual display of alarm status for last 100 shots
- D:** Click on the note to display details for the reject cycle.



Options Tab

The “Options” tab on the eDART® Overview screen will allow access to job setup as well as tools used during processing.



Quality Sampling Tool

The “Quality Sampling” tool will allow you to take sample parts and later correlate the part to the data for that part. This tool marks the shots as samples and creates a new data set.



Process Settings

Clicking on the “Process Settings” button will open the Alarm Limits and Part Sorting control pages.

	Cycle Name	Type	Value	Low	High	Units
<input checked="" type="checkbox"/>	Fill Speed	Alarm	0	2.87	3.52	in/sec.
<input checked="" type="checkbox"/>	End of Cavity #2;A	Alarm	0	2501	9485	psi
<input type="checkbox"/>	End of Cavity #4;A	Alarm	0	2566	9501	psi
<input type="checkbox"/>	Post Gate #1;A	Warning	0	3320	10200	psi
<input type="checkbox"/>	Post Gate #2;A	Alarm	0	3650	10560	psi
<input type="checkbox"/>	Post Gate #2;A	Warning	0	3498	9987	psi

A: You can add alarms, change alarm levels and adjust part sorting controls from this window.

B: Click on Tab you wish to edit.

C: Enter changes to the limits.


D: Any changes made here will be retained until the job is stopped. Once the job is stopped, the changes will be lost unless you save them as a new Master Setup.

*See “Save as Master Setup” section.

Velocity to Pressure Transfer Tool


The Velocity to Pressure Transfer Control Tool allows input of cavity pressure set-points for external Velocity to Pressure Transfer. One side of an OR2-D module will need to be wired to the external transfer input on the Machine.

Click V to P Control, to view where the In-Mold sensor and set-points are selected and set. These controls include Cavity Pressure and Cavity Temperature sensors.



Sensor Name	Status	Setpoint	Units	Enable
End of Cavity #Avg	Inactive	3000	psi	<input checked="" type="checkbox"/>
First stage time exceeds	Inactive	0.50	sec.	<input checked="" type="checkbox"/>
Injection Pressure exceeds	Inactive	10000.00	psi	<input type="checkbox"/>
Injection Volume exceeds	Inactive	0.10	cu. in	<input type="checkbox"/>


Velocity to Pressure Transfer Tool cont.



- E:** Selected Control sensor will be displayed in this box.
- F:** Status of control will show in this box. This will turn to “Active” if it is the first set-point achieved.
- G:** Check this box to enable the set-point control for that sensor.
- H:** Enter set-point for control.
- I:** To remove a control, highlight the row for that control and click the “Remove Control” button.

Velocity to Pressure Transfer Tool cont.

Secondary Controls Tab



K: Check the box to enable set-point. More than 1 can be selected for additional backups.

L: Enter set-point values for each control backup selected.



M: Use this button to test the control output. Click on the “Test Controls” button, the light should turn green and the LED on the OR2-D module should also light.

The Velocity to Pressure Transfer Control tool will transfer the machine to pressure control based on which set-point it sees first. Therefore, any set-point that is enabled will become a backup in case the cavity pressure fails.



Saving Master Setup

If new templates, alarms or control set-points are needed for a new material, color or cavitation, you can save the settings as a new Master Setup. If the changes are temporary for this run, do not save a new Master Setup and settings will be returned to the original Master Setup when the job is stopped.



- A:** Click on the “Save as New Setup” button from the options tab on the eDART® overview screen of the eDART®.
- B:** Check this box if you want to overwrite the previous setup with the new changes.
- C:** Check this box if you want to save the process changes as a new setup for the Mold.
- D:** Click one “SAVE” to save the process changes. If you click “CANCEL”, no changes will be saved.

Save as Master Setup cont.

When the “Create new Setup” check-box is selected the window will open up to allow entry of the name and notes for the new process.

You've changed the current setup. Would you like to save this as a new setup?

Modify this setup

Create new setup

Setup Name: test


Notes:
11-10-11

CANCEL SAVE

- A:** Check this box to save the setup as a new setup.
- B:** Enter the name of the new setup.
- C:** Enter any notes that you would like to save with the setup.

Add Note Tool

When the “Add Note” button is selected the eDART® will open the Note entry window. The Note will be saved on the last cycle on the Summary Graph and will be available to view from there as well as in analyzer during data analysis.



A: Click on the “Add Note” button from the Options tab on the Main eDART® Screen.

B: Enter the note content in this box.



Cycle Graph


This section describes the features found in the eDART® Cycle Graph portion of the software.

In This Chapter

- 76** Cycle Graph
- 78** Graph Control Menu Auto Scale Curves
- 78** Set Fill Volume at Cursor
- 78** Set Volume Zero at Cursor
- 79** Adding Curves
- 83** Template Controls
- 84** Individual Curve Menu

Cycle Graph

The Cycle Graph is where the real time data is displayed visually. All active sensors will be available to view in the graphical, real time form.




A: Main Graph Area. All real time curves will be displayed in this area.

B: Curve Help Screen. This screen shows sample curves and gives descriptions of important features of each curve.


C: Time span visible on the graph. These values can be changed to show any portion of the graph in detail.

D: On/Off signals including triggers, control outputs and sorting outputs, can be displayed in this portion of the graph.

E: Click this button to maximize or minimize the Cycle Graph.



Cycle Graph cont.



F: Use the plus and minus signs to zoom in and out. The graph will always start from 0 seconds as you zoom.

G: Click this button to overlay all future cycles on the display.

H: Each Curve displayed on the Cycle Graph will have a Curve Identification button. The Curve name will be displayed on the button and will be the color of the curve.

I: Cursor. The cursor can be placed on the graph to view values for curves at specific times.


J: Time into the cycle will be displayed at the top of the cursor.

K: Time Date Stamp for the present shot is displayed here. All shots are differentiated with a time date stamp.

L: Machine I/O, Summary Data Table, and Summary Bar Chart can all be access and displayed by clicking on the arrow on this bar.

M: Click on this gear after selecting your data type. The selection list for that data set will pop up.

Graph Control Menu Auto Scale Curves




A: Click on the “Graph Controls” Menu.

B: Click on “Auto Scale” from the menu. The curves will automatically scale fit the screen.

Set Fill Volume at Cursor

The *eDART*® uses the area under the fill portion of the Injection Curve as an Effective Viscosity Measurement as the area varies directly with variation in viscosity. This value is correct only when calculated during the dynamic fill portion of the cycle. To insure that this is calculated at an appropriate place, the volume at transfer needs to be entered into the *eDART*®.



A: Place the Cursor at transfer on the Cycle Graph.


B: Click on the “Graph Controls” Menu - or right click on the cursor.

C: Click on “Set Fill Volume at Cursor”. The *eDART*® will use the volume measurement at that point as an ending point for the Effective Viscosity Measurements.

Set Volume Zero at Cursor


This is active only when you do not have automatic Screw Run trigger on your machine. It is used to provide a zero volume value to the *eDART*®.

Adding Curves



A: Click on the “Graph Controls” menu.

B: Click on “Add a Curve”. When “Add a Curve” is selected the eDART® will display the Add Cycle Data.



C: Click on the button that represents the type of curve to be added. Machine or Mold Curves will be available for each sensor connected to the system.


D: Choose the type of sensor curve to be added.

E: Choose which location you would like to display for the variable type selected.


F: Click on “Done” to have these changes take place.

Machine I/O, Summary Data Table, and Summary Bar Chart

These functions can be used in the split screen format but they are best used and viewed by clicking on the arrow in the upper right corner and bringing Cycle Graph to a full screen view. (A)




- A:** Bring screen to full view
- B:** Click on the down arrow to see the list of options to view
- C:** Click on the type of Data that you would like to view.
- D:** Before you can see the data, you need to click on the “gear” to the right of the tool bar. It will bring up the options for whichever data set you have chosen to view. (Not for Summary Bar Chart).
- E:** From this list, select the specific things you wish to see. Click on “Save” to view your choices.



Machine I/O

The Inputs or Outputs will be displayed in this area of the graph.

- The thin line signifies the signal is off.
- The wide solid line signifies the signal is on.



Machine Sequence will display the machine triggers

- Injection Forward, Screw Run, Mold Clamped, etc...

Control Outputs will display Control outputs from the eDART®

- V>P Transfer, Excessive Reject output.

Sorting Outputs will display the signals sent to the robot or containment device

- Good Part outputs, etc...

Summary Data Table


- A:** Click on the down arrow
- B:** Select the Summary Data Table button
- C:** Click on the "gear" button to the right of the selection drop down
- D:** Choose the values you wish to view and click on "Done" when finished
- E:** You should see a view similar to this after you click on the "Done".

Name	Value	Tpl	% Tpl	Unit	Name
Average Value:Hold Pressure	5225	---	---	psi	Sequence Time:Fill Time
Sequence Time:Cycle Time	26.6	---	---	sec.	Average Value:Back Pressure
Decompression:Shot Stroke	0.103	---	---	in	Sequence Time:Injection Forward


Summary Bar Chart

Injection molds with hot runner manifolds can be notorious for being out of balance. To bring a mold into balance a molder typically tries running fill-only parts and adjusting tip temperatures until the parts are about the same size or weight. Summary Bar Graph helps simplify the troubleshooting when this happens.

- A:** When using multiple In-cavity pressure sensors, the Summary Bar Chart will show balance over the tool using the sensors in each cavity.
- B:** The viewer tool automatically sets up and scales the bars for the number and range of sensors found. You will not need to click on the gear to choose what you view.
- C:** The Summary Bar Chart makes the visual process of balancing much simpler. You can see the high (fast filling) cavities and lower those temperatures while raising the tip temperatures for the lower bars until they all come into balance.
- D:** Check the balance of other parts of the process using the tabs at the bottom of the screen: filling and packing, pressurization and mold temperature. If the mold has only temperature sensors (no pressure) you can see the balance of the time to reach the sensor (“Time @ temp...”) and the mold temperature at that point (minimum).




- E:** If significantly out of balance, you might see a screen looking like this.
- F:** To bring the other column into view, you will need to un-check the “Auto Scale” and set the bottom value to “0”.




Template Controls

A Template is the blue print for your perfect part. When a template is created the eDART® will display it on the cycle graph as a dotted line for each sensor. The eDART® will also compare each future cycle to the template and calculate the difference between the template and the current cycle.

Before a Template is created the job should be soaked in and stable. Never create a template when job is first started. Fill Volume should be set at cursor before template is created.




- A:** Set up job and let it run until it is stable.
- B:** Click on the “Template Controls” Menu.
- C:** To save a Template, click on the “Save Template” button.
- D:** To choose an existing template, click on the button in front of the name of the one you wish to choose. That will apply the template. To turn the template off, simply click on “None”.
- E:** Choose “Edit” to delete or re-name a current Template
- F:** The limit is 10 templates. This message will appear when the limit has been reached. You will need to delete one in order to add any more.




Individual Curve Menu

Each curve displayed on the Cycle Graph will have its own menu. The menu can be accessed by clicking on the header for the curve.



A: Click on the header for the curve to be modified.

When the curve menu is selected a window will appear with the options for curve modifications.



Individual Curve Menu cont.

EOC #4 (Plastic Pressure, End of Cavity #4) Settings

Scaling

Max Value 14900

Min Value 0.00


Visual

Set Curve Color

Set Units psi

Functions

Remove Curve Ok Cancel



- A:** Scale the graph limits by changing these values with either the arrow buttons or directly enter new values.
- B:** Click on the color button to change the curve color. Choose the new color from the color window.
- C:** Choose the units that you would like to display from the drop down menu.



Summary Graph


This section describes the features found in the eDART® Summary Graph Screen

In This Chapter

- 87** Summary Graph
- 88** Auto Scale All Curves
- 88** Add A Curve
- 89** Remove All Curves
- 90** Add Note at Cursor
- 91** Individual Curve Configuration


Summary Graph

The Summary Graph will track one variable over time. The variable value will be plotted each cycle, therefore trends can be observed using this graph.



- A:** Graph Controls Menu- Use this menu to manage all Summary graph curves.
- B:** Variable header – Variable identification and menu for individual variable curve.
- C:** Note – Notes can be saved with the Summary data. The notes will be displayed in this area.
- D:** Time and Cycle count button – Click this button to display Cycle Total, Cycle Shown, Time Shown, or Time Total.
- E:** Data Range – The data displayed on the graph was created between these dates and times.
- F:** Cursor – Place the cursor by left clicking on a cycle or use arrow keys on the keyboard.
- G:** Full Screen - Use this arrow button to maximize or minimize the graph.
- H:** Zoom – Use the – and + buttons to zoom into the data.
- I:** Time/Date Stamp – The time/date stamp for the shot will be displayed at the top of the cursor.
- J:** Add Note – Notes can be added at cursor location and saved with data.
- K:** Data View - Click on any point in a curve on the Summary Graph and the data from that point will be displayed
- L:** Use the Drop down to change what data set you wish to view.

Auto Scale All Curves




A: Click on the “Graph Controls” Menu.

B: Click on “Auto Scale All Curve”. The eDART® will scale all of the curves on the graph to fit the screen.

C: Choose to turn auto-scale on or off.


Add A Curve



A: Click on the “Graph Controls” menu.


B: Click on “Add A Curve”.

Add A Curve con't.



- A:** Click on appropriate button for desired variable. Machine, Mold, or Material.
- B:** Click on the desired variable type from the left column.
- C:** Click on the check box for the desired sensor location from the right column.


Remove All Curves



- A:** Click on the “Graph Controls” button.
- B:** Click on “Remove all Curves”.

Add Note at Cursor


Notes can be added anywhere in the data using the “Add Note at Cursor” function. The notes are saved with the data and can be read any time the data is analyzed.



- A:** Position the cursor at the cycle where the note is to be added.
- B:** Click on “Add Note”. The add note box will appear when “Add Note” is selected.
- C:** Type note in this area.
- D:** Click on the “Save” button.
- E:** The note will be displayed here. To read the note displayed, click on it.

Individual Curve Configuration

The color, scaling, etc. can be configured for each summary variable.



A: Click on the header for the curve to be altered. When the curve header is selected a menu for the curve configuration will appear.

B: Enter custom curve scaling here.

C: Check this box if you would like to use the auto-scale feature.

D: Click on the color box to change the curve color.

E: Set units for displayed curve by clicking on the drop down button. Choose the units that you would like to display.

F: Add Alarm

G: Add Warning

H: Remove Alarm or Warning

I: Remove selected Curve



eDART® Settings Button


This section describes the features found in the Settings portion of the eDART® software.

In This Chapter

- 93** eDART® Settings Button
- 94** Manage Machines
- 94** Manage Molds/Setups
- 96** Configure eDART®
- 97** Networking Setup
- 99** Serial Ports

eDART® Settings Button


From anywhere in the eDART® you can access the settings pages. The settings button will be at the top of the screen. This button will allow access of the networking setup, Mold and Machine management, security and software version information.



- A:** Open the eDART® “Settings” menu.
- B:** Set Security (see Security Section for more details).
- C:** View machine list and delete unwanted machines.
- D:** View Mold/Setup list and delete unwanted molds or settings.
- E:** eDART® serial number, type and software version.
- F:** Set up the Network, languages, time, etc...

Manage Machines

The “Manage Machines” button allows the user to cleanup machines that are no longer in use.




A: Select a Machine.

B: Click on the “Delete” Button. Confirm the action when prompted.

Manage Molds/Setups

The “Manage Molds Setup” button will allow the user to cleanup Molds that are no longer in use.



A: To remove a Mold highlight the Mold to be removed.

B: Click on the “Delete” button. Confirm the action when prompted.

Manage Molds/Setups cont.

The Manage Setups Tab will allow for management of processes saved.

Select a Setup and Choose Action Below

Molds

Setups

Machine	Mold	Setup	Cavity	Run Stats	Last Run	
Arburg 105	Machine102	123	4	9826473/0		▶
Arburg 105	Manual Test	Merry Christmas Test	4	9826473/0		▶
Arburg 105	Merry Christmas 2	Merry Christmas 3	4	9826473/0		▶
Arburg 105	test	test 3	4	9826473/0		▶
Arburg 105	test	123	4	9826473/0		▶

DELETE




A: To select a setup, click on it to highlight.

B: To delete the setup, select the “Delete” button. Confirm action when prompted.

Configure eDART®

The eDART® Configuration screen allows for configuration of network settings, Languages and eDART® Ports.



- A:** Use this drop down to choose the eDART® Startup Language. German, French, Spanish, and English are available.
- B:** Use this drop down menu to choose the keyboard style.
- C:** Use this drop down menu to choose the default units.
- D:** Use this drop down menu to choose the correct time zone for your area.

Networking Setup

eDART® networking is set up from the Networking tab. Without the use of an *eDART*® Data Manager the *eDART*® will require static IP Addresses set to be on the network. If you are using an *eDART*® Data Manager most things on this page can be made automatic from the EDM.

Configuration

The screenshot shows the 'Configuration' window with the 'Network' tab selected. The configuration fields are as follows:

- A:** IP Address: 192.168.5.80
- B:** Default Gateway: (empty)
- C:** Subnet Mask: 255.255.0.0
- D:** eDART Group: Usability Test Coyle
- E:** Node Number: 80
- F:** Additional Network Gateways button

- A:** If you are not using the RJG *eDART*® Data Manager you will need to enter a static IP address to see the *eDART*® on your network. If you are using an EDM you can configure the EDM to handle the addressing automatically.
- B:** If the *eDART*® is connected through a switch or other smart device, you may need to enter the default gateway here to see the *eDART*® on your network. If you are using an EDM you can configure the EDM to handle addressing automatically.
- C:** If you are not using an EDM you will need to enter the subnet mask here. If you are using an EDM you can set the EDM to configure automatically.
- D:** If you are using the EDM you have the option to use a tool called cross copy. The EDM will automatically copy setups initiated on the *eDART*® to all other *eDART*®s that have the same group name. Enter the group name here if you are using this option.
- E:** To change the node number, type the new Node number here. You must reboot the *eDART*® for the new Node number to take effect.
- F:** To add additional Gateways, click on the “Additional Network Gateways” button.

Networking Setup cont.

Additional Gateways

Additional Gateway

Gateway: **A** Destination: **B** **C**

192.168.5.221	10.11.12.0	D -
---------------	------------	------------

 E

A: Type in additional gate way IP address.


B: Type in Destination address.

C: Click on the “Add” button.

D: Click on the minus sign to remove the gateway.

Serial Ports

The “Configure Ports” tab will allow you to configure serial ports on the eDART® for Touch Screens. The eDART® will configure the touchscreen and add the controls to calibrate the touch screen.



A: Click on the “Serial Port” Tab in the Configurations Window.

B: Choose the correct style of touch screen from the drop down menu.



eDART® Security

This section describes the features found in the eDART® Security Section of the software.

In This Chapter


101 Security

102 Configure Groups

103 Configure Users

104 Change Password or
Security Level

Security



A: Security is pre-set on critical functions. To set security levels for the eDART® click on the 'Settings' button on the top right corner of your screen.

B: Then choose 'Configure Users'.

Administrator

The Administrator will come pre-set with access to everything and a separate password that can be changed once the eDART® is in your facility.

Configure Groups

From this screen you can set the security levels for each group. Later you will assign each user to a specific group based on their security level and access.

Allow Permissions by Checking Boxes

Security Levels Users

Security Item	Group_1	Group_2	Group_3
Configure eDART	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Mold and Machine	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Process	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Save Template	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Security	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Set Fill Volume	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Start & Stop Job	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
V->P Transfer	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

SAVE

BACK

A: Select each software function for which a given group will have access.

B: Select functions for basic users, such as Operators.


C: Select functions for intermediate users, such as Process Technicians.

D: Select functions for advanced users, such as Process Engineers.

E: Save the selections. Enter the Administrator Password when prompted.

Configure Users

Choose the “Users” tab to assign users into groups and establish passwords.



- A:** Click on the “Add” button.
- B:** Enter User First and Last Name of User.
- C:** Enter your password then again to Confirm.
- D:** Select Security level for the user from the drop down menu.

Change Password or Security Level

Touch a User and Select an Action

Security Levels Users

	Name	Security Level
1	Administrator	Administrator
2	John Jones	Group_1
3	Barbara Lockwood	Group_3
4	George Williams	Group_2

ADD DELETE

User Details

First Name:
John

Last Name:
Jones

Change Password

Security Level:
Group_1

CANCEL SAVE

A: Click on the arrow beside the user profile to be modified.

B: Choose the new security level from the drop down menu.

C: Change the password by clicking on the 'Change Password' button.

D: Click on the 'Save' button when all information is entered correctly. Enter the Administrator password when prompted.



Log Files and Raw Data Viewer

This section describes the features found in the Log Files and Raw Data Viewer sections of the *eDART*® software.

In This Chapter

106 Audit Log

107 Diagnostic Page

108 Raw Data Viewer

109 Sensor Data Details

Audit Log

Changes made in the eDART® can be seen on the Log page. The eDART® will report what the change, when it was made and who made it as long as security is enabled.

Date/Time ▲	Activity	User	Detail
2011/12/22 18:52:23	Sensor 08 040 00274:2: loc		
2011/12/22 18:52:23	Sensor 08 040 00274:2: type		
2011/12/22 18:52:23	Sensor 08 040 00274:5: loc		
2011/12/22 18:52:23	Sensor 08 040 00274:5: type		
2011/12/22 18:52:23	Sensor 08 040 00274:6: loc		
2011/12/22 18:52:23	Sensor 08 040 00274:6: type		
2011/12/22 18:52:23	Sensor 08 040 00274:7: loc		
2011/12/22 18:52:23	Sensor 08 040 00274:7: type		
2011/12/22 18:52:23	Sensor 03 305 00036:1: loc		
2011/12/22 18:52:23	Sensor 03 305 00036:1: type		
2011/12/22 19:07:47	Template Saved		
2011/12/22 20:20:05	Template Saved		
2011/12/22 22:04:20	Sensor 00 040 00087:2: loc		
2011/12/22 22:04:20	Sensor 00 040 00087:2: type		
2011/12/22 22:04:20	Sensor 00 040 00087:5: loc		
2011/12/22 22:04:20	Sensor 00 040 00087:5: type		

A: Click on the arrows until the third dot is active. This is the Log page.

B: Scroll to the time/data in which you are interested.

Diagnostic Page

	Serial # ▲	Attached to	Sensor Type	Location	Status
●			Diagnostic Info	Port 1	Ok
●			Diagnostic Info	Port 2	Error
⚠	0004000087:1	Machine	Seq. Module Input	Injection Forward	Valid
⚠	0004000087:2	Machine	Seq. Module Input	First Stage	Valid
⚠	0004000087:3	Machine	Seq. Module Input	Screw Run	Valid
⚠	0004000087:4	Machine	Seq. Module Input	Mold Clamped	Valid
⚠	0004000087:5	Machine	Seq. Module Input	Mold Opening	Stale
⚠	0004000087:6	Machine	Seq. Module Input	Machine in Manual	Valid
⚠	0107500200:1	Machine	Control Output	V->P Transfer	Valid
⚠	0107500212:1	Machine	Sorting Output	Good Control	Valid

A: Click on the arrows to get to fourth dot. This is the diagnostic page.

B: Click on the triangle to display information about sensor status.

Sensor Status 0422400051:1 Post Gate #4 ✕

Preload 0.03053 %

Zero Offset -0.03053 %

Sensor Calibration

Preload should be Green.
 If Preload is Yellow or Red, check the sensor pocket bore for proper depth. Pocket corners need to be sharp, remove any radius.
 Zero Offset should be Green.
 If the sensor is Yellow, the sensor is most likely functional but should be calibrated at your convenience. If the sensor is Red, the sensor is no longer functional. Return the sensor to RJG for Recalibration.

View Raw Data

C: Click on the “View Raw Data” button to display more detailed information about the sensor.

Raw Data Viewer

When the triangle is selected a diagnostic will appear.

S/N:Signal	Attached to	Type	Location	Value	Raw	Accuracy	Status	Last Chg	Failure
01 075 00200:1	Machine	Control Output	V->P Transfer	0			Valid		
		Diagnostic Info	Port 1	6 sensors	438/sec.		Valid	4.079	
04 224 00796:1	Mold	Ejector Pin Force	End of Cavity #1;A	0.000000	0	0.50 %	Valid	4.079	
		Flow Rate	Injection	0.000000	0	0.04 %	Valid	2.639	
01 300 00041:1	Machine	Hydraulic Pressure	Injection	-4.579	-5	1.00 %	Valid	4.051	
		Plastic Pressure	End of Cavity #1;A	0.000000	0	0.50 %	Valid	4.086	
		Plastic Pressure	Injection	-61.08	-5	1.00 %	Valid	4.051	
00 040 00087:5	Machine	Seq. Module Input	Mold Closing	ON	1		Valid	2.414	
00 040 00087:1	Machine	Seq. Module Input	Injection Forward		0		Valid		
00 040 00087:4	Machine	Seq. Module Input	Mold Clamped		0		Valid		
00 040 00087:6	Machine	Seq. Module Input	Machine in Manual		0		Valid		
00 040 00087:3	Machine	Seq. Module Input	Screw Run		0		Valid		
00 040 00087:2	Machine	Seq. Module Input	First Stage		0		Valid		
01 075 00212:1	Machine	Sorting Output	Good Control		0		Valid		
04 600 00127:1	Machine	Stroke	Injection	-0.1597	-127	0.04 %	Valid	2.529	
		System Control Output	Operate		0		Valid		
04 600 00127:2	Machine	Velocity	Injection	0.000000	0	0.04 %	Valid	2.639	
		Volume	Injection	-0.1305	-127	0.04 %	Valid	2.529	

- A:** Make sure that both check boxes are checked when checking sensors to eliminate un-needed data.
- B:** Check this column to see the status of the sensor.
- C:** To display more detailed information about the sensor, highlight the line for that sensor.
- D:** Click on “Data Details”.

Sensor Data Details

When “Data Details” is selected a window will open to show details for selected sensor

The screenshot shows a software window titled "Ejector Pin Force, End of Cavity #3;A" with a red header bar. The window contains several fields for sensor configuration, organized into three horizontal sections. The first section includes fields for Status (Invalid), Active (checked), Type Number (11), Indirect (unchecked), Update Time (1325615678.596), Location Number (16), Invert (unchecked), Change Time (1325601089.125), Data Type (integer), Update Interval (3.9 mSec), Class (real time analog), Notify Proxy (5107), Data Size (4), Info Size (84), S/N Changed Proxy (0), and Owner (Lynx_driver). The second section includes Full Scale (500.00), Units (pounds), Scale Factor (0.152625), Current Offset (-409), Accuracy (1.034 %), Initial Offset (-409), Signed (checked), Resolution (13 bits), and Preload (0.000 pounds 0.0 %). The third section includes Serial Number (100174), Channel Number (1), Attached To (Mold), Firmware Version (2), Last Cal Date (02/12/01), Lynx Protocol Version (1), Next Cal Date (02/12/02), Identifies Equipment (unchecked), Multiples (checked), and Data Type (unsigned integer).

Field	Value
Status	Invalid
Active	<input checked="" type="checkbox"/>
Type Number	11
Indirect	<input type="checkbox"/>
Update Time	1325615678.596
Location Number	16
Invert	<input type="checkbox"/>
Change Time	1325601089.125
Data Type	integer
Update Interval	3.9 mSec.
Class	real time analog
Notify Proxy	5107
Data Size	4
Info Size	84
S/N Changed Proxy	0
Owner	Lynx_driver
Full Scale	500.00
Units	pounds
Scale Factor	0.152625
Current Offset	-409
Accuracy	1.034 %
Initial Offset	-409
Signed	<input checked="" type="checkbox"/>
Resolution	13 bits
Preload	0.000 pounds 0.0 %
Serial Number	100174
Channel Number	1
Attached To	Mold
Firmware Version	2
Last Cal Date	02/12/01
Lynx Protocol Version	1
Next Cal Date	02/12/02
Identifies Equipment	<input type="checkbox"/>
Multiples	<input checked="" type="checkbox"/>
Data Type	unsigned integer