THE HUB® SOFTWARE RELEASE NOTES

Build No. v7.8

Overview

The Hub® software now features warning limits settings and display for alarms on jobs, cycles, summary graph, and some bug fixes.

New Features

Warning Limits

Dashboard

- The Dashboard Part Quality graph now displays total good cycles, good cycles with no alarms, good cycles with warning limits, and reject cycles with reject alarms.

- The Dashboard now includes a new Most Warnings graph that provides each job that has been active within the selected time frame, and lists the machine name, process name, mold name, and number of warning cycles.

Machines

The Machines page now displays the number of warning cycles that have occurred for each machine, if the column is selected for viewing.

Reports

- The Reports Job Overview now displays the number of warning cycles in the Cycles count, and displays any warning cycles on the Last 100 Cycles timeline—warning cycles are yellow on the timeline.

- The Reports Summary Graph Export feature now includes the export of warning cycles.

THE HUB® SOFTWARE RELEASE NOTES

Build No. v7.8

Bug Fixes

Inability to View Part Parents When Not Logged In

When not logged in, a user was not allowed to view part parents.

Incorrect Date Timestamp on Trends Until Export

When viewing trends, date timestamp displayed an incorrect month, however, exported data displayed the correct date timestamp month.

Launching a New Mold is Forced to Transfer A Mold Feature

When a user created a new mold with one assigned part and then selected "Launch a New Mold", the user was forced into the "Transfer a Mold" workflow.

Enabling Template Match After a Job is Running Causes Error in Data Export

When a user exported data from a job that had Template Match enabled after the job had already been running, an error occurred.

Unable to View Notes After Viewing the Data Export Menu on the Summary Graph

When a user viewed the Data Export Menu from the Summary Graph, then navigated away to the Summary Graph to view Notes, the Notes button was unresponsive and the user could not view any Notes.

THE HUB® SOFTWARE RELEASE NOTES

Build No. v7.8