

COPILOT® SYSTEM

RELEASE NOTES

Build No. v11.2.1



Overview

This release of the CoPilot® system features bug fixes.

CoPilot System: Bug Fixes

Changes Not Applied to Cavity Fill Time for Pressure Threshold

When a user modified the pressure threshold for cavity fill time, the changes were not applied.

Missing Summary Values and Unable to Load or Save Templates

When a user running a job viewed the Summary Graph, the summary values were missing and templates would not load or save.

Missing Previous Cycle Values

When a user running a job for an extended period of time viewed the Previous Cycle Values widget, the values were missing.

CoPilot Unresponsive

When a user observing a job running for an extended period of time, the system heap usage reached maximum memory allocation and became unresponsive.