



Overview

This release of the CoPilot™ software features bug fixes for the set fill volume at cursor function on the cycle graph.

Fixed Issues

When a user set fill volume, the software failed to properly calculate process fill time.

When a user set fill volume, then reset fill volume, process fill time failed to be calculated off of the reset fill volume and instead was being calculated off of the set fill volume.