

## Overview

This release of the CoPilot<sup>™</sup> software includes a major bug fix.

The CoPilot system would become unresponsive during a down period if the job is not stopped.